

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 10. W. . .

Luce

COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sec.'s 5-8

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 13" White Pine N 82° E 121 links

"1/4 S NBT"

8" White Spruce N 76° W 43 links

"1/4 S NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from two hemlock B.T.'s, bearing N 39° E 8 links (this is stump bottom). B.T. in good condition bearing S 36° W 14 links. "NBT" very plain on this stump.

Corner found by J. Halbach, District Forester.

Found no evidence of use.

1/4 corner lies 1/2 ch. west of swamp on sand ridge.

Corner placed and witnessed December 4, 1957.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 12/4/57