

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46. NR. 10 W.

Luce COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 4-5-8-9

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER

8" Cedar	S 15° E	32 links
	"S 9 NBT"	
9" Cedar	S 70° W	118 links
	"S 8 NBT"	
9" White Pine	N 88° E	52 links
	"S 4 NBT"	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced section corner from one probable B.T. (white pine bearing S 44 E 51 links). Tree down and rotted. Could find no identifying marks. Found several old blazes on hemlock near corner. Position fits very well with other corners in area.

Corner lies on north edge of swamp.

Corner placed and witnessed December 4, 1957.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 12/4/57
REGISTERED LAND SURVEYOR