

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~4647~~ NR 10 W.

Lucas COUNTY

DESCRIPTION OF CORNER ~~Section corner common to Sections 5, 6, 31, 32~~

DESCRIPTION OF CORNER MONUMENT 1" x 48" Iron Pipe

WITNESSES TO CORNER 5" Jack Pine (NBT) N 65° W 64 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established from old fence lines in area. Fences appear to have been built with a 1.00 chain allowance for road easement. Found evidence of corners 1 mile south; 1 mile north; 1 mile east and 2 miles west.

Corner was placed and witnessed May 11, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 5/23/60