

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~4647~~ NR 10 W

Lucas COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 6 and 31

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 15" Hard Maple (NBT) S 45° E 74 1/2 Links

14" Hard Maple (NBT) S 27° W 143 Links

Corner lies 12 links north of road.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established between east-west fences, which are 1.00 chain apart and in line with fences to north and south.

Corner was placed and witnessed May 11, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 5/23/60