

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~46-47~~ NR 10 W

L u c e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 32, 33, 4, 5

DESCRIPTION OF CORNER MONUMENT 1/2" x 36" Iron Bar buried in center of road.

WITNESSES TO CORNER 12" Soft Maple (NBT) S 7° E 82 Links

8" Soft Maple (NBT) N 20° E 62 1/2 Links

Corner lies in center of road.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED. This corner was re-established by single proportionate measure along east and west township line. This position falls in center of blacktop road and 30 links east of fence line to south.

Corner was placed and witnessed June 2, 1960 with Daniel Bonner, Ass't D.F.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 9/14/60