

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46-47 NR. 11 W.

Lucas COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 2 and 35

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 1 1/4" White Pine (1/4s NBT) N 28° E 22 Links

1 1/4" White Spruce (1/4s NBT) S 20° E 86 1/2 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one probable B.T. a White Pine bearing N 35° E 12 Links. Tree down and in poor condition. Found a notch on this tree which could have been part of bottom blaze. Corner lies 25 Links north of road.

Corner was placed and witnessed May 3, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR
Billy D. Buckler

DATE 5/18/60