

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~4647~~ NR 11 W

Lucas COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 1 and 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 15" Hard Maple (1/4" NBT) S 50° W 16 Links

13" Hard Maple (1/4" NBT) S 50° W 15 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established midway and on line between two section corners. Found no evidence of original corner. Found old blazes both east and west of corner.

Corner was placed and witnessed May 12, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

Billy D. Buckler

DATE 5/23/60