

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T~~46847~~ NR 11 W

L u c e COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 1, 2, 35, 36

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 6" W. Pine (NBT) N 87° E 110 Links

8" W. Pine (NBT) N 48° E 111 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established from stream 90 Links west; stream 70 links south; foot of hill 1.23 chains south; foot of hill 1.00 chain north and corners east and west along township line. Found old Cedar stub which has been blazed near corner.

Corner was placed and witnessed May 12, 1960 with Frank J. Bray.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 5/23/60

Billy D. Buckler