

STATE OF MICHIGAN  
DEPARTMENT  
OF  
NATURAL RESOURCES

LAND CORNER RECORD


Luce COUNTY  
T 46N R 11W

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 5-6-7-8

CORNER MONUMENT 2" iron pipe

DATE MONUMENT PLACED AND WITNESSED 11-4-71

WITNESSES TO CORNER..... 50" W. Pine Stump (s8 NBT) S8°E 36.3'



14" B. Cherry (s7 NBT) S62°W 62.4'

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Re-witnessed 2" iron pipe placed by unknown surveyor. Pipe lies on NW corner of a pine plantation. Found no evidence of original corner or witnesses.

SURVEYOR'S SEAL

*Billy D. Buckler*

DISTRIBUTION:

SIGNED Billy D. Buckler DATE 12-7-71  
REGISTERED LAND SURVEYOR

County Courthouse  
Area Forester (Regions I & II)  
District or Region Surveyor  
Forestry Div., Lansing

R 4047  
Rev. 10/68