LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. 3 Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 46 N. ~~S.~~, R. 12 ~~E.~~ W.	A-4, G-4, G-6
2. PROPERTY CONTROLLING IN SECTION	,T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	,T. N. S., R. E. W.	

4. LOT NO. , RECORDED PLAT

5. PRIVATE CLAIMS

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 10-31-74 & 8/76, 19, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on, 19, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

A-4 Quarter Corner on Westside of Section 7, set by Wm A. Burt, D.S. Aug. 28, 1841.
Bearings were: Maple 8", S70°W, 2 lks and Maple 7", N61°E, 21 lks.
G-4 Quarter Corner bet. Sec's. 9-10, set by Francis Colman, D.S. in 1851.
Bearings were: W. Pine 10", N34W, 15 lks. and Maple 6", S23°E, 32 lks.
G-6 Quarter Corner bet. Sec's. 15-16, set by Francis Colman, D.S. in 1851.
Bearings were: W. Birch 18", N34°W, 29 lks. and Beech 12", S63°E, 9 lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

A-4 Corner re-established midway and on line bet. two Sec. Corners. No evidence of original corner.
G-4 Re-established corner bet. two Section Corners.
G-6 Re-established corner midway and on line bet. two Sec. Cors.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Placed 1" pipe with 4" aluminium cap at all corners.

A-4 New Bearings: 10" W. Pine, S22°W, 66.4' and Twin Spruce, N52°W, 101.5'.
G-4 New Bearings; 8" Oak, N35°W, 32.7' and 8" R. Pine, N60°E, 5.4'.
G-6 New Bearings: 12" Hemlock, S39°E, 42.5' and 10" Hemlock, S82°W, 30.7'.

SIGNED BY Billy D. Buckler DATE 1-28-77
Billy D. Buckler
SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

STATE OF MICHIGAN BILLY D. BUCKLER LAND SURVEYOR NO. 8887 REGISTERED LAND SURVEYOR

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY DATE
CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY DATE
MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET