MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T_46 NR_12_F_

	MiceCOUNTY
DESCRIPTION OF CORNE	R _1/4 Corper between Sections 5 & 4
DESCRIPTION OF CORNER	MONUMENT_IF Pipe with AT Bress cap
WITTNESSES TO CORNE	3
	No Mitness Trees Available

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Two original P.T.'s still in place, one good condition, one fair.

Corner was placed and witnessed June 22, 1052.

SURVEYORS SEAL

SIGNED LAND SURVEYOR DATE 3/13/53