

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 46N N.R. 12W


Luce COUNTY

DESCRIPTION OF CORNER East 1/16 corner bet. Secs. 21 & 28

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 6-11-69

WITNESSES TO CORNER..... 12" Cedar (E 1/16 BT) S41°W 16.0°



CIRCLE CORNER REGISTERED

6" E. Spruce (1/16 BT) N53°W 6.2°

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner placed midway and on line between Sec. Cor. to east and $\frac{1}{2}$ corner to west.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler DATE 7-25-69
REGISTERED LAND SURVEYOR