

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 8 & 9W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 12-13 T47N R9W & 7-18 T47N R8W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 4/1/64 with Forestry Aide Leubick and R. Hinds

WITNESSES TO CORNER..... 5" Tamarack (S7 NBT), N52°E, 62½ Lks.



7" Tamarack (S12 NBT), N53°W, 78 Lks.

4" Tamarack (S13 NBT), S74°W, 76 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from scribed wood post. One original B.P. Now a dead stub.
(6" Tamarack, S88°E, 11 Links) in poor condition.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/17/1964
REGISTERED LAND SURVEYOR