

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 8-9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner for Secs. 1, T47N R9W and 6, T47N R8W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8/17/65 with L. Kubick

WITNESSES TO CORNER..... 18" Hemlock (1/4S NBT), S 58° E, 39½ Lks.



14" Hemlock (1/4S NBT), S 12° W, 58 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from point of old wood post and scribed cedar stub by unknown Surveyor. Corner checks well for being on line and proportioned distance between Section Corners.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/19/1965
REGISTERED LAND SURVEYOR