

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47-48 N.R. 3-9 W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner for Secs. 1, T47N R9W, 6, T47N R8W
36, T48N R9W, 31, T48N R8W

CORNER MONUMENT 1" Iron Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 8/17/65 with L. Rubick

WITNESSES TO CORNER..... 10" S Maple (S6 NBT), S 59° E, 32 Lks.



12" S. Maple (S36 NBT), N 48° W, 61 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from down scribed post, found rotted point. Blaze on Birch faces corner. Measurement to Corners in vicinity check well.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/19/1965
REGISTERED LAND SURVEYOR