## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was set from 2 down cedar with proper bearing and distance. Possible scribe mark on one to SE.

SURVEYOR'S SEAL

CINCLE CORNER REGISTERED -