

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9 W


Luce COUNTY

DESCRIPTION OF CORNER E 1/16 between 12-13

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/3/65 with L. Rubick

WITNESSES TO CORNER..... 6" Cedar (E 1/16 BT), N 79° W, 25 Lrs.



10" Spruce (E 1/16 BT), S 71° E, 41½ Lrs.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was placed midway and on line between 1/4 Corner to West and Section Corner to East.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE _____
Frank J. Bray
REGISTERED LAND SURVEYOR