

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9 W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner for Secs. 1-2-11-12

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 8/19/1965 with L. Rubick

WITNESSES TO CORNER..... 9" S. Maple (S1 NBT), N 55° E, 32 lks.



7" H. Maple (S11 NBT), S 01° W, 30 1/2 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two Original BT's . (Sugar 9", S 36° E, 56 lks.) is still growing with Iron Marks. Cedar, down, Iron marks in overgrowth visible.

SURVEYOR'S SEAL

SIGNED Frank S. Bray DATE 11/19/1965
REGISTERED LAND SURVEYOR