Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 47-48 N.R. 9 W

	Luce	COUNTY
DESCRIPTION OF CORNER 1/4 Corner for	or Secs. 1, T47N R9186, T48N R91	
CORNER MONUMENT 1" Iron Pipe with	h 4" Aluminum Cap	
DATE MONUMENT PLACED AND WITHESSED 8	/18/65 with L. Rubick	
WITHESSES TO CORNER 6" H. Mapl	e (1/4S MBT), S 01 W, 22 1ks.	
N	e (1/4S NBT), N 71° E, 301 Lis.	
47-9 AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on Line between Section Corners. No Original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 11/19/1965
REGISTERED LAND SURVEYOR