

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

Two Corners

| FOR CORNERS OF-- | LOCATED IN-- | CORNER CODE NUMBER |
|---------------------------------------|--------------------------------|--------------------|
| 1. PUBLIC LAND SURVEY | T. <u>47</u> N. R. <u>9</u> E. | G-3 G-1 |
| 2. PROPERTY CONTROLLING IN SECTION | T. _____ N. S. R. _____ E. | |
| 3. MISCELLANEOUS PROPERTY IN SECTION | T. _____ N. S. R. _____ E. | |
| 4. LOT NO. _____, RECORDED PLAT _____ | | |
| 5. PRIVATE CLAIMS _____ | | |

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on 5/23 1972, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law.

A. Description of original monument and accessories and/or subsequent restoration:

- G-3 Sec. Cor. 3-4-9-10.
- G-1 Sec. Cor. 3-4, on North Boundary of Township.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

- B-3 Found 6" concrete monuments, set by Luce Co. Rd. Comm. 50.0' to East and 50.0' to west of corner location, which is in center of hwy. M-123.
- B-1 Found 6" concrete post, set by Luce Co. Rd. Comm., 50.0' East of corner, which lies 0.6' West of center of Hwy. M-123.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- C-3 Re-witnessed Corner
New Bearings: 16" W. Pine N41°E 89.0' and 12" W. Pine N70°W 66.0'
- C-1 Re-witnessed Corner
New Bearings: 14" Red Maple N57°W 61.6' and 10" Red Maple N62°E 62.7'

SIGNED BY Billy D. Buckler DATE 12/15/72

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY _____ MICHIGAN REGISTERED LAND SURVEYOR DATE _____ (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____