

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 17-20

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/63

WITNESSES TO CORNER..... 12" Jack Pine (1/2 S MBT) S42°E 24 Lks.



10" Jackpine (1/2 S MBT) S70°W 43 Lks.

10" Jackpine (1/2 S MBT) N16°W 62 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two Pine B.T.s bearing N73°W 145 Links and N21½°E 154 Links. Both B.T.s in fair condition. Found down wood post at Corner.

SURVEYOR'S SEAL

Billy D. Buckler.
SIGNED BILLY D. BUCKLER DATE 7/31/1964
REGISTERED LAND SURVEYOR