

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 15-16

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/16/63

WITNESSES TO CORNER..... 8" Jackpine (1/2 S NBT) S27°W 14 Lks.



8" Jackpine (1/2 S NBT) N55°W 48 Lks.

Corner lies 20 Links North of Murphy Creek Road.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Section Corners.
No evidence of Original Corner.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED BILLY D. BUCKLER DATE 8/3/1964
REGISTERED LAND SURVEYOR