

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 16-21

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 10/16/63

WITNESSES TO CORNER..... 7" Jackpine (1/4 S NBT) S20°E 40 lks.



6" Jackpine (1/4 S NBT) S65°W 54 lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was re-established midway and on line between two Section Corners.  
No evidence of Original Corner.

**SURVEYOR'S SEAL**

SIGNED *Billy D. Buckler*  
BILLY D. BUCKLER DATE 8/3/1964  
REGISTERED LAND SURVEYOR