

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 16-17-20-21

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/63

WITNESSES TO CORNER..... 6" Jackpine (S17 NBT) N42°W 51½ Lks.



6" Jackpine (S20 NBT) S50°W 07 Lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was re-established by Double Proportionate measure from good corners,  $\frac{1}{2}$  mile North;  $\frac{1}{2}$  mile West; 3 miles South and  $1\frac{1}{2}$  miles East.

**SURVEYOR'S SEAL**

SIGNED *Billy D. Buckler*  
BILLY D. BUCKLER  
REGISTERED LAND SURVEYOR

DATE 8/3/1964