

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 31-32

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/6/63

WITNESSES TO CORNER..... 8" Jackpine (1/2 S NBT) N71° W 19 lks.



6" Jackpine (1/2 S NBT) N13° E 14 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on a straight line between two Section Corners. No evidence of Original Corner..

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 8/3/1964