

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 21-22

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/63

WITNESSES TO CORNER..... 4" B. Spruce ($\frac{1}{2}$ S NBT) S50°E 14 Lks.



4" B. Spruce ($\frac{1}{2}$ S NBT) N 10°E 08 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from one Tamarack B.T. bearing N82°W 97 Links.
Tree standing and in fair condition.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
BILLY D. BUCKLER DATE 7/31/1964
REGISTERED LAND SURVEYOR