

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 16-17

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/63

WITNESSES TO CORNER..... 15" Cedar Stump (1/2 S NBT) S80°E 11 Lks.



12" Cedar (1/2 S NBT) S82°W 64 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from two Cedar B.T.s bearing N5°E 05 Links (a stub with overgrowth) and S75°W 37 Lks., a Cedar down. Both B.T.s' in poor condition.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 7/31/1964