

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 17-18-19-20

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/10/63

WITNESSES TO CORNER..... 9" Jack Pine (S19 NBT) S19°W 28 lks.



5" Jack Pine (S20 NBT) S53°E 17 lks.

6" Jack Pine (S18 NBT) N21°W 23 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced as set by H. Lawrence, Registered Land Surveyor. Position checks with Corners South, East and West. Found no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
BILLY D. BUCKLER DATE 7/21/1964
REGISTERED LAND SURVEYOR