

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N. R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 13-14-23-24

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/12/63

WITNESSES TO CORNER..... 10" W. Pine (S24 NBT) S41°E 27½ Lks.



12" Y. Pine (S13 NBT) N76°E 56 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was replaced from B.T., 24" W. Pine S32°W, 321 Links which is a dry snag with Scribe Marks on upper face plainly visible.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
BILLY D. BUCKLER DATE 7/30/1964
REGISTERED LAND SURVEYOR