

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 33-34

CORNER MONUMENT 1" Iron pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/13/63

WITNESSES TO CORNER..... 14" Tamarack ($\frac{1}{4}$ S NBT) S50°E 13 $\frac{1}{2}$ Lks.



12" Tamarack ($\frac{1}{4}$ S NBT) S66°W 22 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on Line between Section Corners $\frac{1}{2}$ mile to North and South. No Original evidence.

SURVEYOR'S SEAL

Billy D. Buckler
SIGNED BILLY D. BUCKLER DATE 7/30/1964
REGISTERED LAND SURVEYOR