

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER Section Corner common to Secs. 26-27-34-35

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/13/63

WITNESSES TO CORNER..... 10" Jack Pine (S26 NBT) N71°E 11½ lks.



8" Jack Pine (S27 NBT) N12°W 19 lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was re-established by double Proportionate Measurement from Corners 1½ miles East, 3 miles West, 1 mile South and ½ mile North.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*  
BILLY D. BUCKLER  
REGISTERED LAND SURVEYOR

DATE 7/30/1964