

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 35-36

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 9/13/63

WITNESSES TO CORNER..... 6" B. Spruce ($\frac{1}{2}$ S NBT) N03°E 27 lks.



12" Jack Pine ($\frac{1}{2}$ S NBT) S52°E 96 lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on line between Section Corners.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR

DATE 7/30/1964