Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 46-47 N. R. 9W

	Luce	COUNTY
DESCRIPTION OF CORNER 1/4 Corner between Secs. 6	-31	
CORNER MONUMENT 1" Pipe with 4" Aluminum Cap		
DATE MONUMENT PLACED AND WITNESSED 7/6/63		
WITHESSES TO CORNER 8" Cedar (2S NBT) N46°W	36 Iks.	
8" Cedar (\$\frac{2}{4}\$ NBT) \$1^0E	29 Iks	
47-9 AND		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established by Single Proportion ate measure along Township line. Corner lies on a North-South fence line.

SURVEYOR'S SEAL

	Billy & Bus	ples
310HED _	BILLY D. BUCKLER	DATE <u>8/3/1964</u>