

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 13-24

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-2-62

WITNESSES TO CORNER..... 14" Red Pine (1/4 S NBT) N56°W, 21 links



10" W. Pine (1/4 S NBT) S53°E, 30 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old scribed cedar post apparently set by H. Lawrence, Registered Land Surveyor. Found cedar B. T. in poor condition bearing SE 08 links. Found scribed 5" spruce at corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 26, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler