

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47N N.R. 9N


Luce COUNTY

DESCRIPTION OF CORNER  $\frac{1}{4}$  corner between sections 11-14

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 7-31-62

WITNESSES TO CORNER..... 8" W. Pine ( $\frac{1}{4}$ S NBT) S 24°E, 87 $\frac{1}{2}$  links



6" B. Spruce ( $\frac{1}{4}$ S NBT) S49°W, 82 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one White Pine B.T. bearing S49°W, 56 links. B.T. has been recently cut. Found all scribe marks on both faces in excellent condition. Corner lies 3/4 ch. west of road.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler* DATE March 7, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler