Cons. 4047 Rev. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 47N H.R. 9W

		Luce	COUNTY
DESCRIPTION OF CORNER	Section corner 23-24-25	:–2 6	
CORNER MONUMENT	l" pipe with aluminum	cap.	
DATE MONUMENT PLACED AND W	THESSED 7-24-62 with	L. Rubick, Aide	<u> </u>
WITMESSES TO CORNER	8" B. Spruce (S25 N	BT) S48°E, 47 links	
25	8" Cedar (S24 NBT)	N40°E, 37 links	
CINCLE COMMEN REGISTERED -	MD		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at post set by H. Lawrence, Registered land surveyor.

SURVEYOR'S SEAL

REGISTERED LAND SURVEYOR Billy D. Buckler