

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N. R. 9 W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 10-15

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 6/19/64

WITNESSES TO CORNER..... 8" Cedar (1/2 S NBT) S57° E, 14 Lks.



12" Cedar (1/2 S NBT) N17° E, 11 1/2 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was placed midway and on Line between Section Corners. No Original evidence found.

SURVEYOR'S SEAL

SIGNED Frank J. Bray DATE 8/18/1964
REGISTERED LAND SURVEYOR