

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 9W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 corner between sections 26-27

CORNER MONUMENT 1" pipe with 1/2" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 8-1-62

WITNESSES TO CORNER..... 5" Jackpine (1/4 S NBT) S70°E 38 links



5" Jackpine (1/4 S NBT) N50°E 46 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at wood post set by Kimberly-Clark cruisers. Found a Y.Pine stump bearing N26°E, 114 links, for probable bearing tree. Corner lies 1 chain south of road.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE March 7, 1963
REGISTERED LAND SURVEYOR
Billy D. Buckler