LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Luce Co. Three Corners.

FOR CORNERS OF—:	LOCATED IN—:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. S., R. 10 E. W.	E-4, D-3, D-5
2. PROPERTY CONTROLLING IN SECTION	T. N. S., R. E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION	T. N. S., R. E. W.	
4. LOT NO. , RECORDED PLAT		
5. PRIVATE CLAIMS		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram – over) were, in a field survey on 6/25 1973, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on 19 , found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

This Twp. originally set by Geo. H. Cannon D.S. in 1853, while making a correctional Survey of this twp.

E-4 Cor. bet. Sec. 8-9. Bearings were: Hemlock 12", N85°E, 17lks.
Maple 10", S88½°W, 61lks.

D-3 Cor. bet. Sec. 5-8. Bearings were: B. Ash 12", S61°W 61lks.
Balsam 10", N61°E 8½lks.

D-5 Cor. bet. Sec. 8-17. Bearings were: Spruce 8", N26°W, 21lks.
Hemlock 10", S60°E, 8lks.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

E-4 Corner re-established in south edge of marsh and at record distance from swamp edge and Sec. Cor. to South. Found no evidence of original corner.

D-3 Set Cor. at sq. post by R. J. Brotherton, R.L.S. dated 10-11-61.

D-5 Set at base of old, scribed, balsam, marked as corner by unknown surveyor. Found blazed east-west blazes, near corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4 1" x 36" pipe with dept. cap. Bearings: 12" W. Pine, S5°E, 21.6'
(Corner lies on South edge of swamp) 12" R. Pine, S58°W, 16.4'

D-3 1" x 36" pipe with dept. brass cap. Bearings: 8" Hemlock, N13°E, 20.1'
8" Cedar, S35°E 8.3'
(Corner lies on SW edge of ridge- Center, NW-SE)

D-5 1" x 36" pipe with dept. cap. Bearings: 14" W. Pine, N66°W, 18.3'
14" W. Pine, S86°E, 27.0'
(Corner lies 130' west of old N-S r.r. grade)

SIGNED BY Billy D. Buckler Billy D. Buckler DATE 8-13-73

SURVEYOR'S MICHIGAN REGISTRATION NO. 69.7 (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY CHIEF OF SURVEY PARTY DATE

APPROVED AND SIGNED BY MICHIGAN REGISTERED LAND SURVEYOR DATE (SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

Form No. ML M736
DOUBLEDAY BROS. & CO., KALAMAZOO, MICH.

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
DISTRIBUTED BY MICHIGAN SOCIETY OF REGISTERED LAND SURVEYORS