Coms. 4047 REV. 10/60

MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9-10W

		Lace	COUNTY
DESCRIPTION OF CORNER _	1/4 Corner between Se	ecs. 1 25-30	
CORNER MONUMENT	Pipe with 4" Aluminum (Cap	
DATE MONUMENT PLACED AN	ID WITHESSED 7/2/63		
WITHESSES TO CORNER	. 14" Camarack (28 II	37) M15 ⁰ E 17 Fs.	
N			
N I			
30			
	AND		
CIRCLE CORNER REGISTERS	0		

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two mection Corners. Found no evidence of Original Corner.

SURVEYOR'S SEAL

Silly D. Buckler.

OCCUPANT TO THE PART OF THE PA

DATE 7/31/1964