

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 9-10W


Ice COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 31-36

CORNER MONUMENT 1" Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 7/2/63

WITNESSES TO CORNER..... 8" Cedar (1/2 S MBT) S89°W 09 1/2 Lks.



8" Cedar (1/2 S MBT) N40°W 54 Lks.

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This Corner was re-established midway and on line between two Section Corners.
Found no evidence of Original Corner.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 7/31/1964
BILLY D. BUCKLER
REGISTERED LAND SURVEYOR