MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 47 NR 10 W

		-		COUNT
OF	CORNER	1/4 corner between	een Sec.'s 29-30	
OF	CORNER	MONUMENT_1"	pipe_with_4" brass	_cap
то	CORNER	12" Jack pine	S 67° E	100½ links
		16" W. Pine	S 56° W "1/4 S NBT"	112 links
	OF	OF CORNER	OF CORNER MONUMENT_1". TO CORNER12" Jack pine	OF CORNER 1/4 corner between Sec. 22-30 OF CORNER MONUMENT 1" pipe with 4" brass TO CORNER 12" Jack pine S 67° E 16" W. Pine S 56° W

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced 1/4 corner from original tamarack line tree 8.65 chs. south.

Found no evidence of 1/4 corner. Extended line north from section corner 29-30-31-32 thru line tree and placed 1/4 corner at record distance.

Corner lies in old road bed.

SURVEYORS SEAL

SIGNED Silly Suckles DATE 11/13/57 _ REGISTERED LAND SURVEYOR