

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 NR 10 W

Luce COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 29-30-31-32  
DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap  
WITNESSES TO CORNER 10" Hard Maple S 55° W 77½ links  
9" Elm "S 31 NBT" N 43° W 108 links  
"S 30 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner. Found 3/4" iron pin and wood stake. Position checks very good to pond and line tree to north and to pond and marsh to east. Found stump holes in proper position for bearing trees.

Found by District Forest personnel. Corner lies 1.00 chs. west of  $\frac{1}{2}$  of county road.

SURVEYORS SEAL

0

SIGNED Billy D. Buckles DATE 11/13/57  
REGISTERED LAND SURVEYOR