

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47 N.R. 10-11 W


Luce COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 19, 30, 24, 25

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/9/60 with L. Rubick, Aide.

WITNESSES TO CORNER.....10" Hard Maple (S 24 NBT) N 83° W 108 Links



CIRCLE CORNER REGISTERED

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced as set by unknown Surveyor. Found scribed wood post and 1½" Iron Pipe in place. No evidence of original corner. Position checks with corners north and south along township line. Found by L. Rubick, Aide. Corner lies in a round opening.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 5/25/61
REGISTERED LAND SURVEYOR
Billy D. Buckler