MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

T. 47 M.R. 10-11 W

		Luce	COUNTY
Section corner (common to Section:	18, 19, 13,	24
1" Pipe with 4"	Brass Cap	 	
D WITNESSED	9/9/60 with 1	L. Rubick, Aid	le
.8" W. Pine	(S 13 NBT)	N 88° W	49 1/2 Links
7" W. Pine	(S 24 NBT)	s 53° W	44 1/2 Links
AND			
	1" Pipe with 4" D WITHESSED	1" Pipe with 4" Brass Cap D WITNESSED 9/9/60 with 1 .8" W. Pine (S 13 NBT) 7" W. Pine (S 24 NBT)	Section corner common to Sections 18, 19, 13, 1" Pipe with 4" Brass Cap 9/9/60 with L. Rubick, Aid 8" W. Pine (S 13 NBT) N 88° W 7" W. Pine (S 24 NBT) S 53° W

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old fence Iron and wood post, Set by unknown surveyor.

Found 24° W. Pine Stump bearing N 77° E. 27 Links, for one probable B.T. Blazes
and axe marks on stump. Placed location poster 14 chains north on road. Corner
found by L. Rublek, Aide.

SURVEYOR'S SEAL

SIGNED Silly O. Sciebles DATE 5/25/61

REGISTERED LAND SURVEYOR

BYLLY D. Buckler