

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 10-11 W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 13 and 18

CORNER MONUMENT 1" Pipe with 4" Brass Cap

DATE MONUMENT PLACED AND WITNESSED 9/9/60 with L. Rubick, Aide.

WITNESSES TO CORNER.....7" W. Pine (1/4s NBT) S 48° E 29 Links



7" W. Spruce (1/4s NBT) N 76° W 13 1/2 Links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced at old scribed wood post set by unknown surveyor. No evidence of original corner. Distance south 39.97 chains to good corner. Post found by L. Rubick, Aide,

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE 5/25/61  
REGISTERED LAND SURVEYOR

Billy D. Buckler