

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 47 N.R. 9&10W


Luce COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Secs. 1, T47N R10W & 6, T47N R9W

CORNER MONUMENT 1" Iron Pipe with 4" Aluminum Cap

DATE MONUMENT PLACED AND WITNESSED 3/25/1964 with Forestry Aide Rubick, Hinds & Alatalo

WITNESSES TO CORNER..... 6" J. Pine ( $\frac{1}{2}$ S MBT) S85°E 08 $\frac{1}{2}$  Lks.



5" J. Pine ( $\frac{1}{4}$ S MBT) N58°W 14 Lks.

AND

CIRCLE CORNER REGISTERED

**DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.**

This Corner was placed on Line and Single Proportioned distance between Section Corners 1/2 mile to North and South.

SURVEYOR'S SEAL

*Frank J. Bray*  
SIGNED Frank J. Bray DATE 8/11/1964  
REGISTERED LAND SURVEYOR