

# LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970

Luce Co.

3 Corners

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY	T. 47 N. R. 10 E.	B-6
2. PROPERTY CONTROLLING IN SECTION	T. 47 N. R. 10 E.	9-Sec. 16 16-Sec. 16
3. MISCELLANEOUS PROPERTY IN SECTION	T. _____ N. R. _____ E.	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 4-28, 1981, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

**A. Description of original monument and accessories and/or subsequent restoration:**

- B-6 Center Corner, Section 18
- 9-Sec. 16 East 1/16 Corner, Section 18
- 16-Sec. 16 East 1/16 Corner, Bet. Sections 18-19

**B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:**

- B-6 Corner established at intersection of lines connecting opposite 1/4 Corners.
- 9-Sec. 16 Placed corner midway bet. 1/4 corner to East and Center Corner to West.
- 16-Sec. 16 Placed corner midway bet. Sec. Cor. to East and 1/4 Corner to West.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

- Placed 1" pipe with 4" alum. cap at all corners. Bearings:
- B-6 6" R. Maple, N20°E, 28.4' & 10" R. Maple, S7°E, 9.8' & 7" R. Maple, S80°W, 13.0'
  - 9-Sec. 16 8" W. Pine, S70°W, 60.3' & 12" W. Pine, S29°W, 33.1' & Center Line Co. Road 407, East, 43.0'.
  - 16-Sec. 16 9" R. Maple, N10°W, 44.0' & 10" R. Maple, S32°E, 41.2' & Center Line Co. Road 407, 120.0' West.

SIGNED BY Billy D. Buckler DATE 5-15-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHIEF OF SURVEY PARTY

APPROVED AND SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_