## LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 LUCE CO. 2 CORNERS.

	FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
	1. PUBLIC LAND SURVEY	T S., R 1	E	
	2. PROPERTY CONTROLL- ING IN SECTION	7. 47 N., R. 10	B-8, 9	
	3. MISCELLANEOUS PROPERTY IN SECTION—	,T N. R I	E	
	4. LOT NO , REC	ORDED PLAT		
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
	I, Gerald L. Wiggins	, do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970, 5-26- , 19 88, established.
	re-established, monumented, re- and rules therefore as required Bureau of Land Management or and 5 above were, in a field surv	monumented, recovered or in the current manual of sur by a decree of a court of la rey on	restored as expressed below and revey instructions of the United S. w. Furthermore, that the corne, 19, found, recovered, res	5-26-, 19 88, established, d in conformance with regulations states Department of the Interior, er points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
B- 8	A. Description of original monument and accessories and/or subsequent restoration: Center of Section 19. Not previously set.			
9	9 East 1/16 Corner of Section 19. Not previously set.			
B- 8	B. Description of corner eviden Corner set at intersec	ce found and/or method ap tion of N-S and E-W	plied in restoring or re-establishing 1/4 Lines by closed to	ng corner: Laverse.
9	Corner set M.P.O.L. between Center Corner and the East 1/4 Corner of Section 19.			
DNR	C. Description of monument for MONUMENT SET AT BOTH CO	corner and accessories esta RNERS.	blished to perpetuate locating the	e position of the corner:
B- 8	10" Balsam, S13°E, 20. 10" Maple, S57°W, 24. 10" Maple, N76°W, 15. 16" Pine, S28°W, 38. Iron W/L.S. Cap #11359	3' 8' 9'	8" Maple, 8" Maple.	N74°E, 18.0' S65°W, 18.55' N71°W, 32.0' N01°W, 23.3' Cap #11359, N85°W, 42.55'

SIGNED BY\_ Gerald L. Wiggins

SURVEYOR'S MICHICAN REGISTRATION NO.

