

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 47N N.R. 11W


Luce COUNTY

DESCRIPTION OF CORNER Sec. Cor. common to Secs. 15-16-21-22

CORNER MONUMENT 1" pipe with 4" aluminum cap

DATE MONUMENT PLACED AND WITNESSED 4-24-70

WITNESSES TO CORNER..... 10" Soft Maple (S21 NBT) S56°W 12.7'



13" Soft Maple (S15 NBT) N24°E 21.8'

AND

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner replaced at an old wood post, set by unknown surveyor.
Found no evidence of the original witnesses.
Position checks well with an original corner, $\frac{1}{2}$ mile south and a corner, one mile north.
Corner lies 100' north of a road intersection.

SURVEYOR'S SEAL

SIGNED *Billy D. Buckler*
Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 1-19-71